



Important Notice for the 1000BASE-T Copper GBIC Transceiver



Incorrect Recognition of 1000BASE-T Copper GBIC in Ethernet Detail Field

- 1 The Ethernet Detail field and Web views incorrectly report the 1000BASE-T Copper GBIC as "Unqualified GBIC". The 1000BASE-T Copper product is operating correctly.

The 1000BASE-T Copper GBIC is supported on the following products:

3C16811

3C16815

3C16816

3CB9FG9

3CB9LG4

3CB9RG4

- 2 .The 1000BASE-T Copper GBIC does not support auto-negotiation.



2

Important Notice for the 1000BASE-T Copper GBIC Transceiver